This is just a sample of the spare parts available to club members contact the spares officer for more details			
ITEM	PART NO.	PRICE	
NOTE: PARTS ARE ONLY AVAILABLE TO JCCA FULL MEMBERS			
• LED Dashboard screw-in bulbs (both – and + earth)	987-LED	\$2.00	
• Lower Trunnion Bushes (4 required per car).	50314	\$36.72	
• Exhaust valves – Stainless Steel.	50516-SS	\$25.00	
• Full Hydraulic master cylinder kits.	SPO1209	\$33.79	
• Lower Javelin radiator hoses are back in stock (black, silicone)	50752	\$12.20	
• New $5\frac{3}{4}$ " headlights Sealed beam.	52102-SB	\$12.70	
Semi-sealed beam.(no bulb).	52102SSB	\$12.70	
• New 7" headlights Halogen sealed beam.	51562HSB	\$16.20	
Javelin Standard Front Seat (needs restoration)	S100/03	Free to the Needy	
• Javelin Flat Plain Crankshaft, crack tested, contact me for sizes.	52010	\$180.00	
• Javelin Water Pump rebuild kit.	54384-KT	\$59.95	
Includes			
2 x 50602 seals			
1 x 50611 SL bearing			
1 x 50853 cover gasket			
2 x 50600 Shortlube bearings			
2 x 54011 Oil cups.			
• Javelin Thermostat Kit.			
Includes			
1 x 50768 Thermostat.	50768	\$21.84	
1 x 4022x3 circlip			
1 x 6228x1 packing washer(s/s)			
1 x 6228x2 rubber washer.			
Bradford rear axle backing plate to backing plate.		\$50.00	

25/08/2020 Page 1 of 2

This is just a sample of the spare parts available to club members contact the spares officer for more details			
ITEM	PART NO.	PRICE	
NOTE: PARTS ARE ONLY AVAILABLE TO JCCA FULL MEMBERS			
• Bradford steering wheel, cracks in covering (could refill and paint).		\$20.00	
Bradford CC engine and gearbox. Engine turns freely and has compression, clutch is OK but flywheel could do with skim (checked by Brian Holmes)		\$200.00	
• A few Jowett transfers.		\$2.00	

25/08/2020 Page 2 of 2